

# Dismantlement of the Tanks No. 10 and No.5 in H4 Tank Area

<Reference>  
September 18, 2013  
Tokyo Electric Power Company

- We started to dismantle the tank No.10 located on the south of the tank No.5 in H4 tank area on September 13 and completed the work by September 16.
- We started to dismantle the tank No.5 on September 17. As of 3:00 PM on September 18, the top and side plates (up to 3<sup>rd</sup> out of 4<sup>th</sup> layers) have been already removed. We plan to remove the side plate (2<sup>nd</sup> layer), and investigate and specify where water leaked from.



No.10 Completion of the side plate removal (3<sup>rd</sup> layer)  
(Photo taken on Sep. 14, 2013)



No.10 Completion of the side plate removal (1<sup>st</sup> layer)  
(Photo taken on Sep. 16, 2013)



No.10 Completion of reinforcement for the bottom plate  
(Photo taken on Sep.16, 2013)



No.5 Top plate removal  
(Photo taken on Sep. 17, 2013)



No.10 Joint between the side plate (1<sup>st</sup> layer) and the bottom plate (inside)  
(Photo taken on Sep. 15, 2013)



No.10 Gathering of rust at a side plate  
(Photo taken on Sep. 15, 2013)



No.10 Sealed part  
(Photo taken on Sep. 15, 2013)



No.5 Completion of the side plate removal (3<sup>rd</sup> layer)  
(Photo taken on Sep. 18, 2013)