


Condition of the Bank Protection Area at Fukushima Daiichi Nuclear Power Station


<Reference>
September 30, 2013
Tokyo Electric Power Company

■ Transition of the groundwater level between Unit 1 and 2 (August 28 - September 28)




* Automatic measurement data measured by water gauge

■ Progress Status of Ground Improvement Construction between Unit 1 and 2 (As of the Morning on September 30)




* The range of the construction is subject to change depends on the site status.

■ Transition of the groundwater level between Unit 2 and 3 (August 28 - September 28)




■ Progress Status of Ground Improvement Construction between Unit 2 and 3 (As of the Morning on September 30)



* The range of the construction is subject to change depends on the site status.

■ Transition of the groundwater level between Unit 3 and 4 (August 28 - September 28)



* Automatic measurement data measured by water gauge

