

Corrective actions taken for Safety Improvement at Fukushima Daiichi Nuclear Power Station

<Reference>
January 26, 2014
Tokyo Electric Power Company
Fukushima Daiichi D&D Engineering Co.

■ Facing work (around groundwater bypass)



Before the corrective action taken



After the corrective action taken
(barricade was set up around the opening.)

■ Trench filling up work for Unit 3 (Shaft B at Unit 3)



Before the corrective action taken



After the corrective action taken
("Use Safety Belt" sign was installed.)

■ Land Side Impermeable Wall (frozen soil wall) Construction (on the west side of Unit 4 Reactor)



Before the corrective action taken



After the corrective action taken
(Barricade was set up to prevent access.)