



May 20th Dose-measurement Points by camera in the Reactor Building of Unit 1




Ground Plan of 1st Floor
of the Reactor Building of Unit 1



0 500 cps

From the large equipment service entrance to the south side airlock
Taken by TEPCO Pictured on May 20, 2011



0 800 cps

Around the large equipment service entrance
Taken by TEPCO Pictured on May 20, 2011