

## Results of Soundness Test of Fuel Pool Cooling and Filtering System of Unit4, Fukushima Daiichi Nuclear Power Station

We connected a temporary water-supply line to the pipes of fuel pool cooling and filtering system (FPC-68) and let air and water into it. We confirmed the soundness of the pipes.

