
< Reference > October 8,2011 Tokyo Electric Power Company

Fukushima Daiichi Nuclear Power Plant Photo Collection






Overview of reactor building of Unit 1 –From south direction of Main Anti-Earthquake Building -October 8, 2011 by TEPCO employee



Overview of reactor building of Unit 1 – From a crane above Unit 1-September 9, 2011 by Cooperating Company Employee



Overview of reactor building of Unit 2 -From western hilltop between Unit 2 and 3-September 29, 2011 by TEPCO employee



Overview of reactor building of Unit 3 -From western hilltop between Unit 2 and 3-September 29, 2011 by TEPCO employee



Overview of reactor building of Unit 3 -From a crane above Unit 3-September 24, 2011 by Cooperating Company Employee



Overview of a reactor building of Unit 4 -From western hilltop between Unit 2 and 3-September 29, 2011 by TEPCO employee



Main control room of Unit 1 and 2 September 22, 2011 by TEPCO employee



Outside Monitoring Post Control Panel (Monitoring Post) -Main control room of Unit 1 and 2-September 22, 2011 by TEPCO employee



Silt protector -Around discharge canals of Unit 1-4-September 29, 2011 by TEPCO employee




Steel pipe sheet-pile -Around discharge canals of Unit 1-4-September 28, 2011 by Cooperating Company Employee



Breakwaters for Unit 5 and 6 (Under construction) June 8, 2011 by Cooperating Company Employee



Breakwaters for Unit 5 and 6 September 29, 2011 by TEPCO employee



Breakwaters for Unit 5 and 6 (Complete) October 5, 2011 by Cooperating Company Employee



Breakwaters –From the shore-September 29, 2011 by TEPCO employee



Breakwaters -From the sea-September 29, 2011 by TEPCO employee