


# Situation of Upper Part of Unit 1 Reactor Building, Fukushima Daiichi Nuclear Power Station

October 8, 2011  
Tokyo Electric Power Company



Layout drawing of 5<sup>th</sup> floor of Unit 1 reactor building in Fukushima Daiichi Nuclear Power Station

- Movie was recorded when dust sampling survey was conducted at upper part of reactor building of Unit 1, on October 3, 2011
- The location of the camera is approximate one



Photographer: Tokyo Electric Power Company  
Recording date: October 3, 2011