

The Water Leakage from the Valve Flange around the Demineralizer of the Evaporation Concentration Apparatus in Fukushima Daiichi Nuclear Power Station (Panoramic View)

<Reference>
January 28, 2012
Tokyo Electric Power Company



Leaking Point

Date : January 28, 2012
Photographed by : Tokyo Electric Power Company

**The Water Leakage from the Valve Flange around the Demineralizer
of the Evaporation Concentration Apparatus in Fukushima Daiichi
Nuclear Power Station (Zoom View)**

<Reference>
January 28, 2012
Tokyo Electric Power Company



Date : January 28, 2012
Photographed by : Tokyo Electric Power Company