


< Reference >

March 22, 2012

Tokyo Electric Power Company

**Survey Results of TIP Room in
Ground-floor at Reactor Building,
Unit 2 at Fukushima Daiichi Nuclear
Power Station
(Conducted on March 21, 2012)**

Survey results (Radiation dose rate, etc)





Location	Dose rate [mSv/h]
1	1.1
2	3
3	1.5
4	1.0
5	2.2
6	1.8
7	2.0
8	1.8
9	1.8
10	1.7
11	1.8
12	1.8
13	1.8
14	1.8
15	1.8
16	2.0

 Survey location of dust concentration

Temperature	Humidity
18.7	26.2%

Survey results (Pictures)




Notable damage is not confirmed in TIP system unit

(Reference) Robot access route

Ground-floor at reactor building, Unit 2

Equipments for inner survey of PCV



【Legend】
Dose rate surveyed until February 27

— Robot route

1 The robot was hauled by man to step over equipments such as hose.