

Investigation in the Torus Room on Unit 2 basement floor of the reactor building

April 19, 2012


Tokyo Electric Power Company




東京電力

TEPCO

Access route of the robot (Result)




First Floor of the Reactor Building




Basement Floor of the Reactor Building

Result of the investigation (air dose rate)

Air dose rate in the Torus Room (mSv/h)



Result of the investigation (Photos) 1/3



Direction to PCV



Upper part of the southeast S/C manhole



Southeast S/C manhole


Result of the investigation (Photos) 2/3



Manhole of North S/C




Route of northeast



Upper part of the route
of northeast

Result of the investigation (Photos) 3/3



Lower part of the Torus Room



Upper part of the south route