


Result of Measurement of Aerial Density of Radioactive Materials At Fukushima Daiichi Nuclear Power Station



- | | | |
|--|---|---|
| [1] MP8 | [10] Mountain side of Unit 1 | [19] MP3 |
| [2] Front of Environment Administration Building | [11] North Slope of Unit 1 | [20] MP1 |
| [3] West Gate (At around Partner Companies' Center Welfare Building) | [12] Front of Cornice House | [21] Opening of Unit 4 Reactor Building |
| [4] Yard for Site Storage Items | [13] Front of Main Anti-Earthquake Building | [22] Opening of Unit 3 Reactor Building |
| [5] West Slope of Unit 3 & 4 | [14] Water Treatment Building | [23] Opening of Unit 2 Reactor Building |
| [6] Wild Birds' Forest | [15] Storehouse for Solid Items | [24] Opening of Unit 1 Reactor Building |
| [7] Mountain side of Unit 3 | [16] Pathway in front of Incinerator Entrance | |
| [8] West Slope of Unit 1 & 2 | [17] Front of PP of Unit 5 & 6 | |
| [9] Mountain side of Unit 2 | [18] Switching Station of Unit 5 & 6 | |

[2] Front of Environment
Administration Building

