




Measurement Result of the Water Level and Temperature of the Accumulated Water in Unit 2 Reactor Building Basement at Fukushima Daiichi Nuclear Power Station



 : Measurement point

Measurement Result (June 28, 2012)



Water Level Measurement

Water level measurement

	Measurement point	Water level
	Northeast corner	OP 3160 mm
	Northwest corner	OP 3170 mm
	Southeast corner	OP 3190 mm
	Southwest corner	OP 3050 mm

Temperature measurement

	Measurement point	Temperature
	Northeast corner	31.4
	Northwest corner	32.1
	Southeast corner	30.3
	Southwest corner	30.2

Radiation exposure (Measurement conducted by TEPCO employees)

Planned: 8.70mSv

Actual: 4.02mSv (Maximum)