


The Accumulated Water Found at Unit 2 Radioactive Waste Underground Storage Facility at Fukushima Daiichi Nuclear Power Station





1. Water flowing in from where the pipe penetrates through the wall



2. Accumulated water