

Soundness Investigation of the Unused (Unirradiated) Fuel Removed from Unit 4 Spent Fuel Pool at Fukushima Daiichi Nuclear Power Station

< Reference >
August 28, 2012
Tokyo Electric Power Company

A tie rod was removed from the fuel assembly by moving the unused fuel investigation assist device from the cask decontamination pit onto the operation floor of the common pool. Then the observation of the fuel appearance and detailed investigation were conducted. Tomorrow (August 29), the appearance of another unused fuel will be observed.



1. Fuel investigation



2. Removing a tie rod from the fuel assembly



3. Locknuts



4. Substances found

Photos taken on August 28, 2012 by TEPCO