


# Investigation of the Inside of Unit 3 Spent Fuel Pool Using an Underwater Camera at Fukushima Daiichi Nuclear Power Station (September 26)

September 26, 2012  
Tokyo Electric Power Company

## Underwater camera investigation on September 26

- 17 workers involved
- From around 7:05 AM to around 10:08 AM



Confirmed no damage on the fuel assembly and the fuel storage rack in the area near the steel beam investigated on September 24.



Tip of the H-steel investigated and other H-steel



Part of the H-steel investigated and fuel storage rack



Jib crane and the tip of the H-steel investigated

[Legend]



: Fuel storage rack



: Areas investigated on September 24 and 25



: Area investigated on September 26

\* Photos - are captured images of the underwater camera video recorded on September 26.