

Result of measurement of Iodine 131 in Kashiwazaki-Kariwa Nuclear Power Plant

[Exhaust stack and Exhaust vent of building]

Observation points		①Iodine 131 (Bq/cm ³)	②Upper Detection Limit (Bq/cm ³)	③Upper Concentration Limit in the Air Bq/cm ³ (Limit in announcement)
Exhaust stack	Unit 1	1.3×10 ⁻⁸	4.6×10 ⁻⁹	5 × 10 ⁻⁶
	Unit 2	1.4×10 ⁻⁸	4.5×10 ⁻⁹	
	Unit 3	6.3×10 ⁻⁹	4.9×10 ⁻⁹	
	Unit 4	7.5×10 ⁻⁹	4.8×10 ⁻⁹	
	Unit 5	1.4×10 ⁻⁸	2.5×10 ⁻⁹	
	Unit 6	9.4×10 ⁻⁹	4.9×10 ⁻⁹	
	Unit 7	1.4×10 ⁻⁸	4.9×10 ⁻⁹	
Exhaust vent of service building	Unit 3	2.4×10 ⁻⁸	4.6×10 ⁻⁹	
	Unit 5	1.1×10 ⁻⁸	3.2×10 ⁻⁹	
	Unit 6	9.6×10 ⁻⁹	4.9×10 ⁻⁹	
auxiliary buildings		8.4×10 ⁻⁹	5.4×10 ⁻⁹	
of incineration building (Ar)		< Limit	4.3×10 ⁻⁹	
of incineration building (Oc)		< Limit	5.0×10 ⁻⁹	