

Work Schedule of the Main Inspection/Restoration of the Kashiwazaki-Kariwa Nuclear Power Station in Response to the Niigata-Chuetsu-Oki Earthquake (during 4 Weeks)(1/1)

【Inspection/Restoration Status】

◆From April 10, 2011 (Sun) to May 7, 2011 (Sat)

System / Equipment		Items	April 10 (Sun) to April 16 (Sat)	April 17 (Sun) to April 23 (Sat)	April 24 (Sun) to April 30 (Sat)	May 1 (Sun) to May 7 (Sat)	Status of Inspection / Restoration
Unit 2	Turbine facilities	Turbine inspection	[Blue bar]				High-pressure turbine and low-pressure turbine (A) (B) (C) detailed inspection commenced on Dec. 7, 2009.
	Other facilities	Main transformer inspection	[Blue bar]				Carrying in and installation work commenced on Jun. 15, 2010.
		House transformer inspection	[Blue bar]				Carrying in and installation work commenced on Nov. 30, 2009.
		Excitation transformer inspection	[Blue bar]				Carrying in and installation work commenced on Nov. 30, 2009.
		Main generator inspection	[Blue bar]				Inspection commenced on Mar. 19, 2008.
		Main exhaust duct inspection / restoration	[Blue bar]				Preparation for restoration work commenced on Aug. 9, 2008. Restoration of substructure commenced on Dec. 1, 2008. Restoration work of a duct commenced on Jul. 17, 2010.
	Seismic reinforcement	Seismic reinforcement works such as pipe supports	[Blue bar]				Reinforcement work commenced on Feb. 1, 2011.
		Seismic reinforcement works for reactor building overhead crane	[Blue bar]				Reinforcement work to be conducted from Jul. 31, 2010 to Apr. 15, 2011.
		Seismic reinforcement works for the fuel handling machine	[Blue bar]				Reinforcement work commenced on Jul. 27, 2010.
Unit 3	Reactor facilities	Primary containment vessel closure	[Blue bar]				Closure work commenced on Mar. 3, 2011.
	Verification of system integrity	System functional test	[Blue bar]				System functional test commenced on Nov. 16, 2010.
Unit 4	Turbine facilities	Turbine inspection	[Blue bar]				High-pressure turbine and low-pressure turbine (A) (B) (C) detailed inspection commenced on Aug. 3, 2009. High-pressure turbine and low-pressure turbine (A) (B) (C) restoration work commenced on Jul. 5, 2010.
	Other facilities	Main transformer inspection	[Blue bar]				Carrying in and installation work commenced on Aug. 28, 2009.
		House transformer inspection	[Blue bar]				Carrying in and installation work commenced on Sep. 2, 2009.
		Excitation transformer inspection	[Blue bar]				Carrying in and installation work commenced on Sep. 2, 2009.
		Main generator inspection	[Blue bar]				Inspection commenced on Jan. 15, 2008.
		Inspection of power supply input transformer of the primary loop recirculation system adjustable speed drive	[Blue bar]				Carrying in and installation work commenced on Jun. 12, 2009.
	Seismic reinforcement	Seismic reinforcement works such as pipe supports	[Blue bar]				Reinforcement work commenced on Jan. 17, 2011.
Others	Restoration and reinforcement work for the on-site/ outside roads & slope, etc.	[Blue bar]				Restoration work for roads inside and outside of the site currently in progress. Restoration work of Takamachi Overpass completed on Mar. 31, 2011.	

* Inspection results for each facilities will be announced as soon as they compiled.

* Inspection and restoration work and execution date for each item may alter according to the situation.

* Unit 1, Unit 5, Unit 6 and Unit 7 are in operation.