

Work Schedule of the Main Inspection/Restoration of the Kashiwazaki-Kariwa Nuclear Power Station in Response to the Niigata-Chuetsu-Oki Earthquake (during 4 Weeks)(1/1)

【Inspection/Restoration Status】

◆ From April 24, 2011 (Sun) to May 21, 2011 (Sat)

System / Equipment	Items	April 24 (Sun) to April 30 (Sat)	May 1 (Sun) to May 7 (Sat)	May 8 (Sun) to May 14 (Sat)	May 15 (Sun) to May 21 (Sat)	Status of Inspection / Restoration	
Unit 2	Turbine facilities	[Blue bars]				High-pressure turbine and low-pressure turbine (A) (B) (C) detailed inspection commenced on Dec. 7, 2009.	
	Other facilities	Main transformer inspection	[Blue bars]				Carrying in and installation work commenced on Jun. 15, 2010.
		House transformer inspection	[Blue bars]				Carrying in and installation work commenced on Nov. 30, 2009.
		Excitation transformer inspection	[Blue bars]				Carrying in and installation work commenced on Nov. 30, 2009.
		Main generator inspection	[Blue bars]				Inspection commenced on Mar. 19, 2008.
		Main exhaust duct inspection / restoration	[Blue bars]				Preparation for restoration work commenced on Aug. 9, 2008. Restoration of substructure commenced on Dec. 1, 2008. Restoration work of a duct commenced on Jul. 17, 2010.
	Seismic reinforcement	Seismic reinforcement works such as pipe supports	[Blue bars]				Reinforcement work commenced on Feb. 1, 2011.
		Seismic reinforcement works for reactor building overhead crane	[Blue bars]				Reinforcement work completed on Apr. 15, 2011.
		Seismic reinforcement works for the fuel handling machine	[Blue bars]				Reinforcement work completed on April 26, 2011.
Unit 3	Reactor facilities	[Blue bars]				Closure work commenced on Mar. 3, 2011.	
	Verification of system integrity	[Blue bars]				System functional test commenced on Nov. 16, 2010.	
Unit 4	Turbine facilities	[Blue bars]				High-pressure turbine and low-pressure turbine (A) (B) (C) detailed inspection commenced on Aug. 3, 2009. High-pressure turbine and low-pressure turbine (A) (B) (C) restoration work commenced on Jul. 5, 2010.	
	Other facilities	Main transformer inspection	[Blue bars]				Carrying in and installation work commenced on Aug. 28, 2009.
		House transformer inspection	[Blue bars]				Carrying in and installation work commenced on Sep. 2, 2009.
		Excitation transformer inspection	[Blue bars]				Carrying in and installation work commenced on Sep. 2, 2009.
		Main generator inspection	[Blue bars]				Inspection commenced on Jan. 15, 2008.
		Inspection of power supply input transformer of the primary loop recirculation system adjustable speed drive	[Blue bars]				Carrying in and installation work commenced on Jun. 12, 2009.
	Seismic reinforcement	[Blue bars]				Reinforcement work commenced on Jan. 17, 2011.	
Others	Restoration and reinforcement work for the on-site/ outside roads & slope, etc.	[Blue bars]				Restoration work for roads inside and outside of the site currently in progress.	

* Inspection results for each facilities will be announced as soon as they compiled.

* Inspection and restoration work and execution date for each item may alter according to the situation.

* Unit 1, Unit 5, Unit 6 and Unit 7 are in operation.

* [Blue bars] The works to be suspended for "Golden Week" holidays. ("Golden Week" holidays are from Apr. 29 to May 5.) Periods may alter according to the progress situation of each work and inspection.