



Damage to Yonomori line tower No.27

- photo of landslide: © GeoEye (March 19th, 2011)
- photos from Viewpoint 1 & 2: TEPCO (March 18th, 2011)
- photos of overview: TEPCO (April 12th, 2011)



©GeoEye

