

(Appendix)

Result of Pu measurement in the seawater Fukushima Daiichi Nuclear Power Station

1. Sampling point: Fukushima Daiichi Nuclear Power Station

- North side of water intake for unit 1-4
- Screen of Unit 2 (inside the silt fence)
- Screen of Unit 3 (inside the silt fence)

2. Analytical body: Japan Chemical Analysis Center

3. Results

(Unit: mBq/L)

Sampling point	Date of Sampling	Pu-238	Pu-239, Pu240
North side of water intake for Unit 1-4	May 16	N.D.	N.D.
Screen of Unit 2 (inside the silt fence)		N.D.	N.D.
Screen of Unit 3 (inside the silt fence)		N.D.	N.D.

4. Evaluation:

Pu-238, Pu-239, Pu240 were not detected from the samples measured this time.