


Status of setting Rest Area

Layout of Rest Areas inside Fukushima Daiichi



① Unit5/6 Service Building
Rest Area on 1st floor (from April 22)

Unit5/6 Service Building
Rest Area on 2nd floor (late June)

③ Rest Area in former
Emergency Response
measure Room (from
June 9)

⑦ Rest Area for Operators of Water
treatment facility (from June 9)

Rest Area near Heliport
(late June)

② Rest Area in front of Main Anti-
Earthquake Building
(Part 1) (from May 13)

Rest Area in front of Main Anti-
Earthquake Building
(Part 2) (from June 11)

Rest Area near Forest of wild
birds (late June)

Hitachi Rest Area
(from June 9)

⑤ Rest Area in Company Center
Welfare Building (from May 29)

⑥ Rest Area in Company Center
Welfare Building (from May 28)

④ Toshiba Rest Area
(from May 10)

- <Outline of Rest Areas which is already in-service>
- ① Service Building of Unit5,6 1st floor Rest Area for 40 workers Approx. 120m²
 - ② Rest Area in front of Main Anti- Earthquake Building (Part 1) for 30 workers Approx. 90m²
 - ③ Rest Area in former Emergency Response Measure Room for 180 workers Approx. 560m²
 - ④ Toshiba Rest Area for 160 workers Approx. 400m²
 - ⑤ Rest Area in Company Center Welfare Building for 60 workers, Approx. 180m²
 - ⑥ Rest Area in Company Center Welfare Building for 60 workers Approx. 190m²
 - ⑦ Rest Area for Operators of Water Treatment Facility for 12 workers Approx. 180m²
 - ⑧ Hitachi Rest Area for 120 workers Approx. 180m²

In-service
 In preparation
 ※ Date between () is the begging of service
 means photos are posted after next page

①Rest Area on 1st floor in Unit5/6 Service Building (In-service from April 22)



Date of photo : May 19, 2011 around 2:00PM
Place :Near doorway of 5/6 Service Building



Date of photo : May 19, 2011 around 2:00PM
Place :Doorway in front of Rest Area



Date of photo : May 19, 2011 around 2:00PM
Place :Inside Rest Area



Date of photo : May 19, 2011 around 2:00PM
Place :Inside Rest Area

②Rest Area in front of Main Anti-Earthquake Building (Part 1) (In- service from May 13)



Date of photo : May 19, 2011 around 1:00PM
Place :Doorway of Rest Area



Date of photo : May 19, 2011 around 1:00PM
Place :Inside Rest Area



Date of photo : May 19, 2011 around 1:00PM
Place :Extra clothes (Protective clothing, Under wears)
in Rest Area, storage space



Date of photo : May 19, 2011 around 1:00PM
Place :Facilities in Rest Area (drinkable water in
2nd from left side is, local exhauster on right side, dust sampler
on left side of right air conditioner

③ Rest Area of Former Emergency Response Measure (In-service from June 9)



Photo : June 9, 2011 approx. 3:00PM
Place : Inside Rest Area



Photo : June 9, 2011 approx. 3:00PM
Place : Inside Rest Area



Photo : June 9, 2011 approx. 3:00PM
Place : Inside Rest Area (Local exhauster is in front)



Photo : June 9, 2011 approx. 3:00PM
Place : Inside Rest Area (Drinkable Water Machine)

④ Toshiba Rest Area (In-service from May 10)



Photo : May 15, 2011 around 11:00AM
Place : Appearance of Rest Area



Photo : May 15, 2011 around 11:00AM
Place : Wiping Feet Place in front of Rest Area



Photo : May 15, 2011 around 11:00AM
Place : Inside Rest Area




Photo : May 15, 2011 around 11:00AM
Place : Drinkable Water machines in Rest Area