

Result of Plutonium analysis on Sub-drain water at Fukushima Daiichi nuclear power plant

1. sampling location:

Fukushima Daiichi Nuclear Power Station

Sub-drain of Unit 2

Sub-drain of Unit 5

2. Institution conducted analysis: JCAC

(Unit: mBq/L)

Sample	Sampling date	Pu-238	Pu-239,Pu-240
Unit 2 sub-drain	June 13	N.D. [$<5.1 \times 10^{-1}$]	N.D. [$<4.9 \times 10^{-1}$]
Unit 5 sub-drain		N.D. [$<4.7 \times 10^{-1}$]	N.D. [$<4.7 \times 10^{-1}$]

Values in parentheses indicate measurable limit.

3. Evaluation:

Pu-238, Pu-239 and Pu-240 were not detected from the samples analyzed.

END