
Bq/cm3
Fukushima Daiichi Nuclear Power Station
Results of Dust Nuclide Analysis
1.0E-01
1.0E-02
1.0E-03
1.0E-04
1.0E-05
1.0E-06
1.0E-07
I-131(Total; West Gate)
Cs-134(Total; West Gate)
Cs-137(Total; West Gate)
White marks are additional measurement points
□:I-131 △:Cs-134 ○:Cs-137
①South of Unit 5
②Northeast of administration office bulding
③Northeast of the ground
④Northwest of the ground
⑤West gate
⑥Main gate
⑦Southeast of Skill training center
⑧West of Industrial waste treatment facility
⑨South of Centralized Radiation Waste Treatment Facility
⑩Around MP5
* A point measured today is indicated in red.
Notification Level
Cs-137 (3E-3Bq/cm3)
Cs-134 (2E-3Bq/cm3)
I-131 (1E-3Bq/cm3)
5/22
5/26
5/30
6/3
6/7
6/11
6/15
6/19
6/23
6/27
7/1
7/5
7/9
7/13
7/17
7/21