

Results of Additional Dust Nuclide Analysis to Evaluate the Impact Bq/cm³ from Nitrogen Injection to Primary Containment Vessel 1.0E-01 Additional sampling point :I-131 (Total) South of Unit 5 :Cs-134(Total) Northeast of administration office bulding : Cs-137 (Total) Northeast of the ground Northwest of the ground 1.0E-02 West gate Notification Level Main gate Southeast of Skill training center Cs-137 West of Industrial waste treatment facility (3E-3Bq/cm3) South of Centralized Radiation Waste Treatment Facility Cs-134 Around MP5 (2E-3Bq/cm3) 1.0E-03 In front of Partner company's building I-131 (1E-3Bq/cm3) Around MP-7 South-southwest boundary of Site Around MP8 A point measured today is indicated in red. 1.0E-04 1.0E-05 1.0E-06 1.0E-07 7/1 7/5 5/30 6/3 6/11 6/15 6/19 6/23 6/27 7/9 7/13 7/17 7/21