

Fukushima Daiichi Nuclear Power Station Analysis Result of Plutonium in the Sea Water

1. Place of sampling: Fukushima Daiichi Nuclear Power Station
North of 1F5-6 Discharge Channel
South Discharge Channel
2. Analysis Organization: Japan Chemical Analysis Center
3. Result:

(Unit : mBq/m³)

Place of samples	Date of sampling	Pu-238	Pu-239, Pu-240
1F North of 1F5-6 Discharge Channel	Aug. 15	N.D. [$<5.2 \times 10^{-1}$]	N.D. [$<5.2 \times 10^{-1}$]
1F South Discharge Channel		N.D. [$<4.5 \times 10^{-1}$]	N.D. [$<4.5 \times 10^{-1}$]

Numbers inside [] mean detection limits

4. Evaluation:
No Pu-238, Pu-239 and Pu-240 were detected in the samples for this time.

END