

(Attachment 2)

Sr analysis result in the air at Fukushima Daiichi Nuclear Power Plant

1. Sampling points : Fukushima Daiichi Nuclear Power Plant West gate
2. Analysis Institute: Japan Chemical Analysis Center
3. Results :

(Unit: mBq/m³)

Sampling type	Date	Sr-89	Sr-90
Volatile	10/10	N.D.	N.D.
Particle		N.D.	N.D.

[]:measurable limit

4. Evaluation:

No Sr-89, Sr-90 were detected.

END