

**Work Schedule of the Main Inspection/Restoration of the Kashiwazaki-Kariwa Nuclear Power Station in Response to the Niigata-Chuetsu-Oki Earthquake (during 4 Weeks)(1/1)**

**【Inspection/Restoration Status】**

◆From November 20, 2011 (Sun) to December 17, 2011 (Sat)

System / Equipment	Items	November 20 (Sun) to November 26 (Sat)	November 27 (Sun) to December 3 (Sat)	December 4 (Sun) to December 10 (Sat)	December 11 (Sun) to December 17 (Sat)	Status of Inspection / Restoration
Unit 2	Turbine facilities					High-pressure turbine and low-pressure turbine (A) (B) (C) detailed inspection commenced on Dec. 7, 2009.
	Other facilities					Inspection commenced on Mar. 19, 2008.
	Seismic reinforcement					Reinforcement work commenced on Feb. 1, 2011.
Unit 3	Reactor facilities					Closure work commenced on Mar. 3, 2011.
	Verification of system integrity					System functional test commenced on Nov. 16, 2010.
Unit 4	Turbine facilities					High-pressure turbine and low-pressure turbine (A) (B) (C) detailed inspection commenced on Aug. 3, 2009. High-pressure turbine and low-pressure turbine (A) (B) (C) restoration work commenced on Jul. 5, 2010.
	Other facilities					Inspection commenced on Jan. 15, 2008.
						Carrying in and installation work commenced on Jun. 12, 2009.
	Seismic reinforcement					Reinforcement work commenced on Jan. 17, 2011. Reinforcement work for attached structure of reactor pressure vessel commenced on Jun. 27, 2011.

\* Inspection results for each facilities will be announced as soon as they compiled.

\* Inspection and restoration work and execution date for each item may alter according to the situation.

\* Unit 5 and Unit 6 are in operation, and Unit 1 and Unit 7 are in periodical inspection.