

The Result of analysis for Pu of sub-drains at Fukushima Daiichi

1. Place of sampling: Fukushima Daiichi sub-drain of Unit 1
sub-drain of Unit 2
sub-drain of Unit 5
2. Analytical body : Japan Chemical Analysis Center (JCAC)
3. Sampling result:

(Unit: mBq/L)

Place of sampling	Date of sampling	Pu-238	Pu-239,Pu-240
Sub-drain of Unit 1	11/14	N.D. [$<4.9 \times 10^{-1}$]	N.D. [$<4.9 \times 10^{-1}$]
Sub-drain of Unit 2		N.D. [$<4.7 \times 10^{-1}$]	N.D. [$<4.9 \times 10^{-1}$]
Sub-drain of Unit 5		N.D. [$<5.2 \times 10^{-1}$]	N.D. [$<5.0 \times 10^{-1}$]

[] : Detection Limit

4. Evaluation:

There is no detection of Pu-238, Pu-239 and Pu-240 from this sampling

END