The Result of analysis for Pu in the ocean around Fukushima Daiichi

- 1. Place of sampling : The Unit 5 and 6 North Discharge Channel of Fukushima Daiichi Around South Discharge Channel of Fukushima Daiichi
- 2. Analytical body : Japan Chemical Analysis Center (JCAC)
- 3. Sampling result:

(Unit: mBq/m³)

Place of sampling	Date of sampling	Pu-238	Pu-239,Pu-240
1F 5, 6 North Discharge Channel	11/14	N.D. [<4.9×10 ⁻¹]	N.D. [<4.9×10 ⁻¹]
1F South Discharge Channel		N.D. [<5.0×10 ⁻¹]	N.D. [<5.0×10 ⁻¹]

[]: Detection Limit

4. Evaluation:

There is no detection of Pu-238, Pu-239 and Pu-240 from this sampling

END