

The Result of analysis for Pu in seawater around Fukushima Daiichi

1. Place of sampling : the North of Units 1 to 4 Water Intake of Fukushima Daiichi
2. Analytical body : Japan Chemical Analysis Center (JCAC)
3. Sampling result:

(Unit: mBq/L)

Place of sampling	Date of sampling	Pu-238	Pu-239,Pu-240
the North of Units 1 to 4 Water Intake	11/14	N.D. [$<4.7 \times 10^{-1}$]	N.D. [$<4.4 \times 10^{-1}$]

[] : Detection Limit

4. Evaluation:

There is no detection of Pu-238, Pu-239 and Pu-240 from this sampling

END