



Schematic Diagram of Fukushima Daini Nuclear Power Station



Second floor of service building of unit 3 and 4 of Fukushima Daini Nuclear Power Station

Table next to the small monitor where pollution was found.