



Burns Found in the DC 250V Charger Panel Installed in the Regular Electric Item Room
in the Second Basement of Unit 7 Control Building



Condition inside the charger panel (with the panel back door opened)