

集中廃棄物処理施設周辺 サブドレン水核種分析結果

I-131 (Bq/L)

Table with columns for measurement location (測定場所) and dates from 6/11 to 6/27. Data points are mostly ND (Not Detected) with some values in parentheses.

Cs-134 (Bq/L)

Table with columns for measurement location (測定場所) and dates from 6/11 to 6/27. Data points include ND values and numerical values in parentheses.

Cs-137 (Bq/L)

Table with columns for measurement location (測定場所) and dates from 6/11 to 6/27. Data points include numerical values and ND values in parentheses.

- はサンプリング・測定を実施していないことを示す。
は が採取不可となったため、地下水流の上流側として選定し、週1回程度の頻度で測定。(2011/4/29-)
は地下水流の下流側であることから、追加で測定。(2011/5/26-)
を追加で測定。(2011/5/30-)
を追加で測定。(2011/8/2-)
NDは検出限界値未満を表し、()内に検出限界値を示す。

- < 測定箇所 >
4号T/B建屋南東
プロセス主建屋北東
プロセス主建屋南東
プロセス主建屋南西
雑固体廃棄物減容処理建屋南
サイトバンカ建屋南西
焼却工作建屋 西側
雑固体廃棄物減容処理建屋北
サイトバンカ建屋南東