

集中廃棄物処理施設周辺 サブドレン水核種分析結果

I-131 (Bq/L)

Table with 20 columns for measurement locations and 10 rows of data for I-131. Values include ND (Not Detected) with associated dates in parentheses.

Cs-134 (Bq/L)

Table with 20 columns for measurement locations and 10 rows of data for Cs-134. Values include ND (Not Detected) with associated dates in parentheses.

Cs-137 (Bq/L)

Table with 20 columns for measurement locations and 10 rows of data for Cs-137. Values include ND (Not Detected) with associated dates in parentheses, and some numerical values.

-はサンプリング・測定を実施していないことを示す。  
は採取不可となったため、地下水流の上流側として選定し、週1回程度の頻度で測定(2011/4/29~)  
は地下水流の下流側であることから、追加で測定(2011/5/26~)  
を追加で測定(2011/5/30~)  
を追加で測定(2011/8/2~)  
NDは検出限界値未滿を表し、( )内に検出限界値を示す。

- <測定箇所>  
4号T/B建屋南東  
プロセス主建屋北東  
プロセス主建屋南東  
プロセス主建屋南西  
雑固体廃棄物減容処理建屋南  
サイトバンカ建屋南西  
焼却工作建屋 西側  
雑固体廃棄物減容処理建屋北  
サイトバンカ建屋南東